InspectionSmith 1614 Frances Place Monroe LA 71201 318-243-3912

inspectionsmithmonroe@gmail.com

Report: 901 orleans dr, ruston 01-14-2020

Confidential Inspection Report 901 Orleans Dr Ruston, la

January 14, 2020



Prepared for:

This report is the exclusive property of the inspection company and the client whose name appears herewith and its use by any unauthorized persons is prohibited.

Inspection Table of Contents

Summary	3
GENERAL INFORMATION	5
GROUNDS	7
EXTERIOR - FOUNDATION	9
ROOF SYSTEM	12
ELECTRICAL SYSTEM	16
HEATING - AIR CONDITIONING	20
PLUMBING SYSTEM	23
KITCHEN - APPLIANCES	26
BATHROOMS	28
INTERIOR ROOMS	31
LAUNDRY AREA	34
GARAGE - CARPORT	35
SPRINKLER SYSTEM	36
OUTBUILDING	37

January 14, 2020

,

RE: 901 Orleans Dr Ruston, la



Dear :Twin Creeks Realty

At your request, a visual inspection of the above referenced property was conducted on January 14, 2020. An earnest effort was made on your behalf to discover all visible defects, however, in the event of an oversight, maximum liability must be limited to the fee paid. The following is an opinion report, reflecting the visual conditions of the property at the time of the inspection only. Hidden or concealed defects cannot be included in this report. No warranty is either expressed or implied. This report is not an insurance policy, nor a warranty service.

SUMMARY OF AREAS REQUIRING FURTHER EVALUATION

IMPORTANT: The Summary is not the entire report. The complete report may include additional information of concern to the client. It is recommended that the client read the complete report. The entire Inspection Report, including the Standards of Practice, limitations and scope of Inspection, and Pre-Inspection Agreement must be carefully read to fully assess the findings of the inspection. This list is not intended to determine which items may need to be addressed per the contractual requirements of the sale of the property. Any areas of uncertainty regarding the contract should be clarified by consulting an attorney or real estate agent.

It is strongly recommended that you have appropriate licensed contractors evaluate each concern further and the entire system for additional concerns that may be outside our area of expertise or the scope of our inspection BEFORE the close of escrow. Please call our office for any clarifications or further questions.

Here is a list of concerns that need further evaluation or repair by appropriately Licensed Contractors.

GROUNDS

Patio / Porch: Rear

Slab:

Patio type: Concrete, Cracks noted - typical. Surface raised/settled, Tile floor covering popping up.

Cover / Roof:

Leak around fireplace.

EXTERIOR

Chimney:

Flashing:

Step flashing installed. Leak noted at patio.

Report: 901 orleans dr, ruston 01-14-2020 **Address:** 901 Orleans Dr Page 4

ROOF SYSTEM

Eaves - Soffits - Fascias:
Type & Condition:
Chipping paint noted at fascia.

ELECTRICAL SYSTEM

Electrical Outlets:

General:

A representative sampling of outlets was tested. As a whole, outlets throughout the house are in serviceable condition. Ground Fault Circuit Interrupter (GFCI) outlets are recommended for installation at exterior, garage, bath rooms & kitchen outlets.

Attic Wiring:

Appears serviceable, Open junction boxes are noted.

GARAGE - CARPORT

Garage Door:

Material - Condition:

Deterioration noted at base of door trim.

Other minor items are also noted in the entire inspection report and should receive eventual attention, but do not affect the habitability of the house and the majority are the result of normal wear and tear.

Thank you for selecting our firm to do your pre-purchase home inspection. If you have any questions regarding the inspection report or the home, please feel free to call us.

Sincerely,


Robert Smith LHI#10796 InspectionSmith

GENERAL INFORMATION

Client & Site Information:

Inspector:

Robert Smith Ihi#10796.



Client:

Inspection Date: January 14, 2020 9:00 AM. Inspection Time:

9:00 AM. Twin Creeks Realty.

Inspection Site: 901 Orleans Dr Ruston, Ia.

People Present:

South.

Rain.

Homeowner, Inspector.

Building Characteristics:

Main Entry Faces: Estimated Age:

Not determined.

Age: Building Style & Type:

1 family.

Space Below Grade:Ground floor living area.

Water Source: Public.

Wet.

Sewage Disposal: Public.

Utilities Status: All utilities on.

Stories:

olic.

Climatic Conditions:

Weather:

Soil Conditions:

Outside Temperature (f):

50-60.

About Rated Items:

Items not found in this report are beyond the scope of this inspection and should not be considered inspected at this time. Please read the entire report for important details. Inspected items may be generally rated as follows:

OK = "Serviceable" = Item is functional and we did not observe conditions that would lead us to believe problems existed with this system or component. Some serviceable items may show wear and tear. Other conditions may be noted in the body of the report.

MM = "Marginal/Maintenance" = Item warrants attention and/or monitoring, or has a limited remaining useful life expectancy and may require replacement in the not too distant future. Further evaluation or servicing is needed by a qualified licensed contractor or specialty tradesman dealing with that item or system.

RR = "Repair or Replace" = Item, component, or unit is not functioning as intended and needs repair or replacement. Further evaluation is needed by a qualified licensed contractor or specialty tradesman dealing with that item or system.

REPORT LIMITATIONS

This report is intended only as a general guide to help the client make his own evaluation of the overall condition of the home, and is not intended to reflect the value of the premises, nor make any representation as to the advisability of purchase. The report expresses the personal opinions of the inspector, based upon his visual impressions of the conditions that existed at the time of the inspection only. The inspection and report are not intended to be technically exhaustive, or to imply that every component was inspected, or that every possible defect was discovered. No disassembly of equipment, opening of walls, moving of furniture, appliances or stored items, or excavation was performed. All components and conditions which by the nature of their location are concealed, camouflaged or difficult to inspect are excluded from the report. The inspection is performed in compliance with generally accepted standard of

Report: 901 orleans dr, ruston 01-14-2020 Address: 901 Orleans Dr

Page 6

practice, a copy of which is available upon request.

Systems and conditions which are not within the scope of the inspection include, but are not limited to: formaldehyde, lead paint, asbestos, toxic or flammable materials, and other environmental hazards; pest infestation, playground equipment, efficiency measurement of insulation or heating and cooling equipment, internal or underground drainage or plumbing, any systems which are shut down or otherwise secured; water wells (water quality and quantity) zoning ordinances; intercoms; security systems; heat sensors; cosmetics or building code conformity. Any general comments about these systems and conditions are informational only and do not represent an inspection.

The inspection report should not be construed as a compliance inspection of any governmental or non governmental codes or regulations. The report is not intended to be a warranty or guarantee of the present or future adequacy or performance of the structure, its systems, or their component parts. This report does not constitute any express or implied warranty of merchantability or fitness for use regarding the condition of the property and it should not be relied upon as such. Any opinions expressed regarding adequacy, capacity, or expected life of components are general estimates based on information about similar components and occasional wide variations are to be expected between such estimates and actual experience.

We certify that our inspectors have no interest, present or contemplated, in this property or its improvement and no involvement with tradespeople or benefits derived from any sales or improvements. To the best of our knowledge and belief, all statements and information in this report are true and correct.

Should any disagreement or dispute arise as a result of this inspection or report, it shall be decided by arbitration and shall be submitted for binding, non-appealable arbitration to the American Arbitration Association in accordance with its Construction Industry Arbitration Rules then obtaining, unless the parties mutually agree otherwise. In the event of a claim, the Client will allow the Inspection Company to inspect the claim prior to any repairs or waive the right to make the claim. Client agrees not to disturb or repair or have repaired anything which may constitute evidence relating to the complaint, except in the case of an emergency.

GROUNDS

This inspection is not intended to address or include any geological conditions or site stability information. We do not comment on coatings or cosmetic deficiencies and the wear and tear associated with the passage of time, which would be apparent to the average person. However, cracks in hard surfaces can imply the presence of expansive soils that can result in continuous movement, but this can only be confirmed by a geological evaluation of the soil. Any reference to grade is limited to only areas around the exterior of the exposed areas of foundation or exterior walls. We cannot

determi systems ground, inspecti controlle shrubs, such me	ne drainage performance of the sand municipal water and sewe where no viewing or access is on. We do not evaluate any deed components such as drivew fountains, ponds, statuary, pottention of these items is informatical.	site r serves s pos tache ay ga tery, t	or the vice passible. Set structured to the contraction of the contrac	e con piping Any ucture We its, pa	dition of any underground piping, including subterranean drainage or septic systems. Decks and porches are often built close to the y areas too low to enter or not accessible are excluded from the es such as storage sheds and stables, nor mechanical or remotely do not evaluate or move landscape components such as trees atio fans, heat lamps, and decorative or low-voltage lighting. Any ot to be construed as inspected.
Paving	g Conditions:	OK	MM	RR	
	Driveway:	V			Driveway Type: Concrete, Cracks noted are typical.
	Walks:			1000	Sidewalk type: Concrete, Cracks noted are typical.
	Exterior Stone / Stoons				
Dotio /	Exterior Steps / Stoops: Porch: Rear	V	ш		
ratio i	Slab:		Ø		Patio type: Concrete, Cracks noted - typical. Surface raised/settled, Tile floor covering popping up.
		No. of the last of		X	
	Structure:	$\overline{\mathbf{V}}$			Metal.



Cover / Roof:

RR ☑ OK MM

Leak around fireplace.

metal.





Fences & Gates:

Condition: Type: Chain link. \checkmark

Grading:

Site: Negative grade rear of house.





Landscaping: *Condition:*

 \checkmark Trim plants away from structure.

EXTERIOR - FOUNDATION

All structures are dependent on the soil beneath them for support, but soils are not uniform. Some that appear to be firm and solid can become unstable during seismic activity or may expand with the influx of water, moving structures with relative easy and fracturing slabs and other hard surfaces. In accordance with our standards of practice, we identify foundation types and look for any evidence of structural deficiencies. However, minor cracks or deteriorated surfaces are common in many foundations and most do not represent a structural problem. If major cracks are present along with bowing, we routinely recommend further evaluation be made by a qualified structural engineer. All exterior grades should allow for surface and roof water to flow away from the foundation. All concrete floor slabs experience some degree of cracking due to shrinkage in the curing process. In most instances floor coverings prevent recognition of cracks or settlement in all but the most severe cases. Where carpeting and other floor coverings are installed, the materials and condition of the flooring underneath cannot be determined. Areas hidden from view by finished walls or stored items cannot be judged and are not a part of this inspection. We will certainly alert you to any suspicious cracks if they are clearly visible. However, we are not specialists, and in the absence of any major defects, we may not recommend that you consult with a foundation contractor, a structural engineer, or a geologist, but this should not deter you from seeking the opinion of any such expert. We also routinely recommend that inquiry be made with the seller about knowledge of any prior foundation or structural repairs.

Exterior Walls:

Materials & Condition:

OK ☑	MM	RR	Walls are constructe	ed with Brick.	Cracks noted are typical.
		3			
					4 2 3

Exterior Doors:

Main Entry Door: Side Entry Door: Garage Rear Entry Door:

✓ □ □ Metal, with glass.✓ □ □ Metal, with glass.

Exterio	or Windows:					
	Predominant Type:	OK ☑	MM □	RR	Vertical Sliders.	
	Overall Condition:	$\overline{\checkmark}$			Satisfactory overall, considering age.	
	Type And Condition Of Sills:	$\overline{\checkmark}$			Masonry.	
Chimn					•	
Cililiii	ey. Please Note:	There are a wide variety of chimneys and interrelated components. However, there are three basic types, single-walled metal, masonry, and pre-fabricated metal ones that are commonly referred to as factory-built ones. Single-walled metal ones should not be confused with factory-built metal ones, and are rarely found in residential use, but masonry and factory-built ones are commonplace. Our inspection of them conforms to industry standards, and is that of a generalist and not a specialist. However, significant areas of chimney flues cannot be adequately viewed during a field inspection. Therefore, because our inspection of chimneys is limited to areas easily viewed and does not include the use of specialized equipment, we will not guarantee their integrity or drafting ability and recommend that they be more thoroughly evaluated by a qualified chimney specialist before the close of escrow.				
	Chimney Exterior:				Chimney is constructed of brick materials.	
	Flue:				The inspection is limited to the visible portions of the fireplace flue. Drop light, mirrors, and smoke testing are not a part of the inspection. Visibility is limited to as little as 20% of the flue. If further investigation is recommended, the services of a qualified professional chimney sweep should be obtained.	
	Flashing:					
			$\overline{\checkmark}$		Step flashing installed. Leak noted at patio.	
	Chimney Cap:	Ø			There is a chimney cap. The chimney cap is made of morter. Its function is to keep water from entering the stack and causing deterioration. There is a metal rain hat installed. It will help keep rain from entering the flue. There is a metal spark arrestor installed. In addition to preventing fires, it will also keep animals and birds out of the flue.	

Report: 901 orleans dr, ruston 01-14-2020 Address: 901 Orleans Dr



	1503						
Height & Clearance:	OK ☑	MM	RR □	The chimney installation appears to meet clearance requirements.			
Foundation:							
Materials & Condition:				Poured in place slab concrete. Typical cracks are noted. Shrinkage cracks are hairline cracks that are caused by the evaporation of water in the mix. This is a normal condition. Seventy-five percent of all shrinkage cracks appear in the first year. The exterior view of the foundation is limited to the portions visible above grade. Satisfactory - The exposed portions of the perimeter foundation walls appear to be adequate.			
Recent Movement:				There is no evidence of any recent movement.			

ROOF SYSTEM

Although not required to, we generally attempt to evaluate various roof types by walking on their surfaces. If we are unable or unwilling to do this for any reason, we will indicate the method used to evaluate them. Every roof will wear differently relative to its age, number of layers, quality of material, method of application, exposure to weather conditions, and the regularity of its maintenance. We can only offer an opinion of the general quality and condition of the roofing material.

The inspector cannot and does not offer an opinion or warranty as to whether the roof leaks or may be subject to future leakage. The waterproof membrane beneath roofing materials is generally concealed and cannot be examined without removing the roof material. Although roof condition can be evaluated, it is virtually impossible for anyone to detect a leak except as it is occurring or by specific water tests, which are beyond the scope of our service. Even water stains on ceilings or on framing within attics will not necessarily confirm an active leak without some corroborative evidence, and such evidence can be deliberately concealed. We evaluate every roof conscientiously, and even attempt to approximate its age, but we will not predict its remaining life expectancy, or guarantee that it will not leak. Naturally, the sellers or the occupants of a residence will generally have the most intimate knowledge of the roof and of its history. Therefore, we recommend that you ask the sellers about it, and that you either include comprehensive roof coverage in your home insurance policy, or that you obtain a roof certification from an established local roofing company. We do not inspect attached accessories including by not limited to solar systems, antennae, and lightning arrestors.

_			_
О	_	_	£.
ĸ	C 1	"	_

Style: Hip.

Roof Access: Walked on roof.

OK MM RR

Roof Covering: □ □ □ Composition shingles, Architectural heavy duty design.



Roof Covering Condition:

- ☐ General condition appears serviceable with signs of weatheringand aging. Regular maintenance and inspections are advised.
- □ □ Some moss growth noted in some areas.
- □ □ Patch noted front side of house.







Flashings:

 $\begin{array}{cccc} \mathsf{OK} & \mathsf{MM} & \mathsf{RR} \\ \hline \boxtimes & \square & \square & \mathsf{Metal plumbing vent flashings}. \end{array}$





Valleys:

- OK MM RR
- $\ \square \ \square \ \square$ The valleys appear to be in satisfactory condition.



Eaves - Soffits - Fascias:

Type & Condition:

- □ ☑ □ Chipping paint noted at fascia.





It is our company policy that we do not attempt to enter attics that have less than thirty-six inches of headroom, are restricted by ducts, or in which the insulation obscures the joists and thereby makes mobility hazardous, in which case we would inspect them as best we can from the access point. In regard to evaluating the type and amount of insulation on the attic floor, we use only generic terms and approximate measurements, and do not sample or test the material for specific identification. Also, we do not disturb or move any portion of it, and it may well obscure water pipes, electrical conduits, junction boxes, exhaust fans, and other components.

Attic & Insulation:

Access:	\checkmark		Attic is full size, Viewing was limited.
Structure:			SHEATHING- The roof decking material is 1/2" plywood sheeting. The builder did not install ply clips during installation, which may result in sagging at the joints of the sheeting.
			A rafter system is installed in the attic cavity to support the roof decking.



Insulation:

OK MM RR \checkmark

Blown in cellulose.



Depth & R-factor:

5-6 inches, 8-9 inches.

Ventilation Provisions:

 \checkmark There are soffit vents installed. There is at least one rooftop turbine installed.

ELECTRICAL SYSTEM

We are not electricians and in accordance with the standards of practice we only test a representative number of switches and outlets and do not perform load-calculations to determine if the supply meets the demand. However, every electrical deficiency or recommended upgrade should be regarded as a latent hazard that should be serviced as soon as possible, along with evaluation and certification of the entire system as safe by a licensed contractor. Therefore, it is essential that any recommendations that we may make for service or upgrades should be completed before the close of escrow, because an electrician could reveal additional deficiencies or recommend additional upgrades for which we disclaim any responsibility. Any electrical repairs or upgrades should be made by a licensed electrician. Aluminum wiring requires periodic inspection and maintenance by a licensed electrician. Smoke Alarms should be installed within 15 feet of all bedroom doors, and tested regularly.

Operation of time clock motors is not verified. Inoperative light fixtures often lack bulbs or have dead bulbs installed. The inspector is not required to insert any tool, probe, or testing device inside the panels, test or operate any over-current device except for ground fault interrupters, nor dismantle any electrical device or control other than to remove the covers of the main and auxiliary distribution panels. Any ancillary wiring or system that is not part of the primary electrical distribution system is not part of this inspection but may be mentioned for informational purposes only, including but not limited to low voltage systems, security system devices, heat detectors, carbon monoxide detectors, telephone, security, cable TV, intercoms, and built in vacuum equipment.

Service:

Type & Condition: ☐ ☐ Underground, 110/220 Volt, Circuit breakers.



Grounding Equipment:

☐ ☐ Grounded via rod in ground.

Exterior of house.



Electrical Distribution Panels:

Main Panel Location:




Main Circuit Rating: ☑ □ □ 150 amps.

 $\overline{\mathbf{V}}$

	OK	MM	RR
Entrance Cable Size:	\square		

Service Disconnect Switch:



Main Panel Observations:

☐ Circuit and wire sizing correct so far as visible, Grounding system is present.



 $\overline{\mathbf{V}}$

Conductors:

Entrance Cables:

Branch Wiring:	\square		Copper.
Switches & Fixtures:			
General:	☑		A representative sampling of switches was tested. As a whole, switches throughout the house are in serviceable condition. Lights are not operational in some areas, possibly due to bad bulbs.
Kitchen Interior:			A representative sampling of switches was tested. As a whole switches throughout the room are in serviceable condition.
Master Bath:	\square		A representative sampling of switches was tested. As a whole, switches throughout the room are in serviceable condition.

Aluminum- OK.

- Hall Bath:

 A representative sampling of switches was tested. As a whole, switches throughout the room are in serviceable condition.
- throughout the room are in serviceable condition.
- Entry / Foyer / Hall:

 A representative sampling of switches was tested. As a whole switches throughout the room are in serviceable condition.
- Living Room:

 A representative sampling of switches was tested. As a whole switches throughout the room are in serviceable condition.
- Dining Room:
 ☐ ☐ A representative sampling of switches was tested. As a whole switches throughout the room are in serviceable condition.
- Master Bedroom: □ □ A representative sampling of switches was tested. As a whole switches throughout the room are in serviceable condition.

		OK	MM	RR	
	Bedroom #3: Front				A representative sampling of switches was tested. As a whole switches throughout the room are in serviceable condition.
	Bedroom #4: Office				A representative sampling of switches was tested. As a whole switches throughout the room are in serviceable condition.
	Laundry:				A representative sampling of switches was taken. As a whole, switches throughout this room are ins serviceable condition.
	Garage Walls:	\square			A representative sampling of switches and fixtures were tested. As a whole, switches and fixtures throughout the house are in serviceable condition.
Electri	cal Outlets:				
	General:		\square		A representative sampling of outlets was tested. As a whole, outlets throughout the house are in serviceable condition. Ground Fault Circuit Interrupter (GFCI) outlets are recommended for installation at exterior, garage, bath rooms & kitchen outlets.
	Kitchen Interior:	$\overline{\checkmark}$			A representative sampling of outlets was tested. As a whole, outlets throughout the room are in serviceable condition.
	Master Bath:				A representative sampling of outlets was tested. As a whole, outlets throughout the room are in serviceable condition.
	Hall Bath:				A representative sampling of outlets was tested. As a whole, outlets throughout the room are in serviceable condition.
	Entry / Foyer / Hall:				A representative sampling of outlets was tested. As a whole, outlets throughout the room are in serviceable condition.
	Living Room:	\square			A representative sampling of outlets was tested. As a whole, outlets throughout the room are in serviceable condition.
	Dining Room:	\square			A representative sampling of outlets was tested. As a whole, outlets throughout the room are in serviceable condition.
	Master Bedroom:	\square			A representative sampling of outlets was tested. As a whole, outlets throughout the room are in serviceable condition.
	Bedroom #2:				A representative sampling of outlets was tested. As a whole, outlets throughout the room are in serviceable condition.
	Bedroom #3: Front				A representative sampling of outlets was tested. As a whole, outlets throughout the room are in serviceable condition.
	Bedroom #4: Office	☑			A representative sampling of outlets was tested. As a whole, outlets throughout the room are in serviceable condition.
	Laundry:	\checkmark			Electrical outlet is grounded. 220 not tested.
	Garage Walls:	\square			A representative sampling of switches and outlets was tested. As a whole, outlets and switches throughout the house are in serviceable condition.
Attic V	Viring:				
	Attic & Insulation:		\square		Appears serviceable, Open junction boxes are noted.



Report: 901 orleans dr, ruston 01-14-2020 Address: 901 Orleans Dr Page 19

Ce	il	in	a	F۶	an	S
06	••	•••	9		411	J

	UN	IVIIVI	Γ		
Living Room:				Satisfactory - There is a ceiling fan installed in this room. be functional.	It appears to
Master Bedroom:	\square			Satisfactory - There is a ceiling fan installed in this room. be functional.	It appears to
Bedroom #2:	☑			Satisfactory - There is a ceiling fan installed in this room. be functional.	It appears to
Bedroom #3: Front	$\overline{\mathbf{V}}$			Satisfactory - There is a ceiling fan installed in this room. be functional	It appears to

HEATING - AIR CONDITIONING

The inspector can only readily open access panels provided by the manufacturer or installer for routine homeowner maintenance, and will not operate components when weather conditions or other circumstances apply that may cause equipment damage. The inspector does not light pilot lights or ignite or extinguish solid fuel fires, nor are safety devices tested by the inspector. The inspector is not equipped to inspect furnace heat exchangers for evidence of cracks or holes, or inspect concealed portions of evaporator and condensing coils, heat exchanger or firebox, electronic air filters, humidifiers and de-humidifiers, ducts and in-line duct motors or dampers, as this can only be done by dismantling the unit. This is beyond the scope of this inspection. Thermostats are not checked for calibration or timed functions. Adequacy, efficiency or the even distribution of air throughout a building cannot be addressed by a visual inspection. Have these systems evaluated by a qualified individual. The inspector does not perform pressure tests on coolant systems, therefore no representation is made regarding coolant charge or line integrity. We perform a conscientious evaluation of the system, but we are not specialists.

Please note that even modern heating systems can produce carbon monoxide, which in a poorly ventilated room can result in sickness and even death. Therefore, it is essential that any recommendations we make for service or further evaluation be scheduled before the close of escrow, because a specialist could reveal additional defects or recommend further upgrades that could affect your evaluation of the property, and our service does not include any form or warranty or guarantee. Normal service and maintenance is recommended on a yearly basis. Determining the presence of asbestos materials commonly used in heating systems can ONLY be preformed by laboratory testing and is beyond the scope of this inspection. Determining the condition of oil tanks, whether exposed or buried, is beyond the scope of this inspection. Leaking oil tanks represent an environmental hazard which is sometimes costly to remedy.

Heating Equipment:

Type & Location:

Forced Air.



Fuel Source:

General Operation & Cabinet:

Burners / Heat Exchangers:

RR OK MM

 $\overline{\mathbf{V}}$ Natural Gas.

 \square

Unit was operational at the time of inspection.

 $\overline{\mathbf{V}}$



 $\begin{array}{c|cccc} & & \text{OK} & \text{MM} & \text{RR} \\ \textit{Pump / Blower Fan:} & & \boxdot & \Box & \Box \\ \textit{Combustion Air:} & & \boxdot & \Box & \Box \\ \end{array}$

Flue, Vents, Plenum: \square \square The flue pipe is plastic from the furnace to the exterior.

Air Filters: ☑ □ □



Normal Controls: \square \square Thermostat is located in the hall.



Fireplaces / Solid Fuel Heating:

 \square \square Gas logs. Not fully tested. Possible air in line.



Living Room:

Air Conditioning:

Primary Type: Central, Split System-



Brand: Carrier brand.

OK MM RR

Fuel Source: □ □ □ 220 Volt, Electrical disconnect present.

Air Temp Drop:

16 F Considered acceptable.



System Condition: □ □ □ General condition appears serviceable.

Condensate Line:

Normal Controls: ☑ □ □

Ductwork / Distribution:

Ducts / Air Supply: □ □ Insulated sheet metal, Flexible Round.

Air Intake/Filters: Filter(s) are Disposable types.

Report: 901 orleans dr, ruston 01-14-2020 **Address:** 901 Orleans Dr Page 23

PLUMBING SYSTEM

Water quality or hazardous materials (lead) testing is available from local testing labs, and not included in this inspection. All underground piping related to water supply, waste, or sprinkler use are excluded from this inspection. Leakage or corrosion in underground piping cannot be detected by a visual inspection, nor can the presence of mineral build-up that may gradually restrict their inner diameter and reduce water volume. Plumbing components such as gas pipes, potable water pipes, drain and vent pipes, and shut-off valves are not generally tested if not in daily use. The inspector cannot state the effectiveness or operation of any anti-siphon devices, automatic safety controls, water conditioning equipment, fire and lawn sprinkler systems, on-site water quality and quantity, on-site waste disposal systems, foundation irrigation systems, spa and swimming pool equipment, solar water heating equipment, or observe the system for proper sizing, design, or use of materials.

The water pressure within pipes is commonly confused with water volume, but whereas high water volume is good high water pressure is not. Therefore a regulator is recommended whenever street pressure exceeds 80 psi. However, regardless of pressure, leaks will occur in any system, and particularly in one with older galvanized pipes, or one in which the regulator fails and high pressure begins to stress washers and diaphragms within various components.

Waste and drainpipes pipe condition is usually directly related to their age. Older ones are subject to damage through decay and root movement, whereas the more modern ABS ones are virtually impervious to damage, although some rare batches have been alleged to be defective. Older homes with galvanized or cast iron supply or waste lines can be obstructed and barely working during an inspection but later fail under heavy use. If the water is turned off or not used for periods of time (such as a vacant house waiting for closing), rust or deposits within the piping can further clog the piping system. However, inasmuch as significant portions of drainpipes are concealed, we can only infer their condition by observing the draw at drains at the time of inspection. Nonetheless, blockages will still occur in the life of any system.

observi	ng the draw at drains	at the time	of ins	specti	on. I	Nonetheless, blockages will still occur in the life of any system.		
Main L	ine:							
	Shut Off:		Fron	t yard				
	Material:		Not viewed.					
	Pressure:		Water pressure appears adequate.					
Supply	Lines:							
,	Material:		Cop	per.				
			OK	MM	RR			
	Condition:					General condition appears serviceable.		
Waste	Lines:							
	Material:		Plas	tic.				
	Condition:		$\overline{\checkmark}$			General condition appears serviceable.		
Hose E	Bibs / Hookups:							
	General:					Sample operated, appeared serviceable.		
connect	ed to a drain line of	proper size a drain ext	term endir	ninatir	ng jus	tion of the water heater is a required safety valve which should be st above floor elevation. If no drain is located in the floor a catch fe location. The steam caused by a blow-off can cause scalding.		
Water	Heater:							
Power S	Source:	Capacity:				Location:		
Gas.		40 Gallons.				Garage closet.		



Condition:

OK MM RR

- ☑ □ □ Appears serviceable, Pressure relief valve noted, not tested, Flue vent intact, A water shutoff valve is installed. older unit limited life expectancy.
- □ □ □ Due to location unit should be on a stand 18 inches off the ground or have a raised burner, due to age of house this was not a standards, recommend changing when unit is replaced, do not store flamable material in this room.



Fuel System:

Meter / Tank:

☑ □ □ Meter located at exterior, System appears serviceable, main shut off is located at meter. Left side of house.



See Bathrooms section of report for information about plumbing and fixtures in those areas.

Fixtures & Drain

Kitchen Sink:

- ☑ □ Stainless Steel, Faucet is serviceable.
- ☑ □ □ under sink drain appears serviceable.





Hose Bibs / Hookups/Sink Faucets:

☐ Plumbing appears serviceable.



KITCHEN - APPLIANCES

We may test kitchen appliances for basic functionality, but cannot evaluate them for their performance nor for the variety of their settings or cycles. Appliances older than ten years may exhibit decreased efficiency. Even if general comments are made, these items are not inspected: free-standing appliances, refrigerators, freezers, ice makers, trash-compactors, built-in toasters, coffee-makers, can-openers, blenders, instant hot-water dispensers, water-purifiers, barbecues, grills, or rotisseries, timers, clocks, thermostats, the self-cleaning and cooking capability of ovens, and concealed or countertop lighting, which is convenient but often installed after the initial construction and not wired to national electrical standards. These items should be considered outside the scope of the inspection. Appliances are not moved during the inspection. Portable dishwashers are not inspected, as they require connection to facilitate testing.

Range/	Coo	kton	/ Ov	/en·
Nance		NLUD	<i>1</i> • • • • • • • • • • • • • • • • • • •	vell.

OK MM RR Electric, Appears serviceable. Type & Condition: $\overline{\mathbf{Q}}$



Ventilation:

Type & Condition: External, Fan/Hood operational.



Refrigerator:

Type & Condition: Not part of inspection.

Dishwasher:

Condition:

 \square General condition appears serviceable.





Garbage Disposal:

Condition: \square General condition appears serviceable.



Kitchen Interior:

Counters:

OK MM RR ☑ □



Counters & Backsplashes:

oxdots oxdots General condition appears serviceable.



Cabinets:

☑ □ □ Wood.

BATHROOMS

In accordance with industry standards of practice, we do not comment on common cosmetic deficiencies, and do not evaluate window treatments, steam showers, and saunas. More importantly, we do we leak-test shower pans, which is usually the responsibility of a termite inspector. However, because of the possibility of water damage, most termite inspectors will not leak-test second floor shower pans without the written consent of the owners or occupants.

Our inspection of interior areas includes the visually accessible areas of walls, floors, cabinets and closets, and a representative number of windows and doors, switches and outlets. We do not evaluate window treatments, nor move furniture, lift carpets or rugs, empty closets or cabinets, and we do not comment on common cosmetic deficiencies.

Sink & Cabinetry:

OK MM RR

Master Bath: □ □ Fixture appear serviceable.

□ □ □ Drain appears serviceable.

 $\overline{\mathbf{V}}$





Hall Bath:

 \square \square Fixture appear serviceable.







Toilet:

Master Bath: ☑ □ General condition appears serviceable.



Hall Bath:

☐ ☐ General condition appears serviceable.



Tub/Shower Fixtures:

Master Bath:

OK MM RR

oxdot general condition of fixtures appears serviceable.



Hall Bath:

 $\ \square \ \square \$ general condition of fixtures appears serviceable. Hot and cold may be reversed.





Tub/Shower And Walls:

Master Bath: Hall Bath: ☑ □ □ Shower walls appear serviceable, Enclosure appears serviceable.☑ □ □ Shower walls appear serviceable, Enclosure appears serviceable.

Bath Ventilation:

Master Bath:

 \square \square General condition appears serviceable.



Hall Bath:

☐ ☐ ☐ General condition appears serviceable. The switches for the heat and vent are miss labeled.



Report: 901 orleans dr, ruston 01-14-2020 Address: 901 Orleans Dr Page 31

INTERIOR ROOMS

Our inspection of living space includes the visually accessible areas of walls, floors, cabinets and closets, and the testing of a representative number of windows and doors, switches and outlets. We do not evaluate window treatments, move furnishings or possessions, lift carpets or rugs, empty closets or cabinets, nor comment on cosmetic deficiencies. We may not comment on cracks that appear around windows and doors, along lines of framing members or along seams of drywall and plasterboard. These are typically caused by minor movement, such as wood shrinkage, common settling, and seismic activity, and will often reappear if they are not correctly repaired. Such cracks can become the subject of disputes, and are therefore best evaluated by a specialist. Floor covering damage or stains may be hidden by furniture, and the condition of floors underlying floor coverings is not inspected. Determining the condition of insulated glass windows is not always possible due to temperature, weather and lighting conditions. Check with owners for further information. All fireplaces should be cleaned and inspected on a regular basis to make sure that no cracks have developed. Large fires in the firebox can overheat the firebox and flue liners, sometimes resulting in internal damage. Testing, identifying, or identifying the source of environmental pollutants or odors (including but not limited to lead, mold, allergens, odors from household pets and cigarette smoke) is beyond the scope of our service, but can become equally contentious or difficult to eradicate. We recommend you carefully determine and schedule whatever remedial services may be deemed advisable or necessary before the close of escrow.

General Comments:

An occupied house such as this one will typically have furniture, storage and other items that will partially block areas from inspection. Closets are usually packed with items which can completely block access and/or inspection. It is recommended that you inspect these areas at the walk through before your closing. Report any adverse findings to your representative prior to closing.

This home is older and the home inspector considered this while inspecting. It is common to have areas that no longer comply with current code. This is not a new home and this home cannot be expected to meet current code standards. While this inspection makes every effort to point out safety issues, we do not inspect for code. It is common that homes of any age will have had repairs performed and some repairs may not be in a workmanlike manner. Some areas may appear less than standard. This inspection looks for items that are not functioning as intended. We do not grade repairs. It is common to see old or mixed materials. Sometimes signs of damage could be years old from a problem that no longer exists. Or, it may still need further attention and repair. Determining this can be difficult on an older home.

Molds are a part of the natural environment. They play an essential role breaking down organic matter. However, we do want to avoid the interior growth of these organisms. Molds reproduce by means of spores. These spores float through the air and are invisible to the naked eye. That is why the ONLY way to know if mold is present in a home is with proper sight sampling lab tests. Molds only begin to grow when these spores land on wet surfaces. There is no mold growth possible without moisture. Changes in building practices over the years have moved us toward tighter and more energy efficient houses. The emphasis has been on sealing and insulating to keep air-conditioned air in, and outside air out. There are many sources of moisture that occur indoors. They can become trapped and give rise to the main condition conducive to mold growth - moisture. Newer construction materials like sheetrock and particle board provide the necessary food, primarily cellulose, necessary for mold to grow. It is important for you to understand that molds are found in every home. The questions are what types of mold are present, how prevalent are they, can we effectively eliminate and/or manage the moisture that makes their growth possible and how will the occupants react to their presence. Please be aware that the inspector has your best interest in mind. Any items mentioned in this report should be considered before purchase. It is recommended that qualified contractors be used in your further inspection of issues as it relates to the comments in this inspection report.

Doors: OK MM RR Overall Interior Door Condition: OK MM RR General condition of doors throughout the home are in serviceable

condition. Some doors may need some minor adjustments.

Master Bath: ☑ □ □
Hall Bath: ☑ □ □

	E (OK	ММ	RR	
	Entry / Foyer / Hall:	☑			
	Living Room:	☑			
	Master Bedroom:	\square			
	Bedroom #2:				
	Bedroom #3: Front				
	Bedroom #4: Office				
	Laundry:				
Windo	ws:				
	General Type & Condition:	V			Aluminum, A representative sampling was taken. Windows as a grouping are generally operational.
	Kitchen Interior:				
	Living Room:	$\overline{\checkmark}$			
	Dining Room:	$\overline{\checkmark}$			
	Master Bedroom:	$\overline{\checkmark}$			
	Bedroom #2:	$\overline{\checkmark}$			
	Bedroom #3: Front	$\overline{\checkmark}$			
	Bedroom #4: Office	$\overline{\checkmark}$			
Walls:					
vvaiis.	General Material & Condition:	V			Drywall, Paneling, General condition appears serviceable, Typical cracks noted.
	Kitchen Interior:	$\overline{\checkmark}$			
	Master Bath:	$\overline{\checkmark}$			
	Hall Bath:	\checkmark			
	Entry / Foyer / Hall:	$\overline{\checkmark}$			
	Living Room:	$\overline{\checkmark}$			
	Dining Room:	$\overline{\checkmark}$			
	Master Bedroom:	$\overline{\checkmark}$			
	Bedroom #2:	$\overline{\checkmark}$			
	Bedroom #3: Front	Ø			There is some minor cracking in the sheetrock. Most likely this is due to slight settlement or shrinkage.
				L	
			1	-	THE PERSON NAMED IN COLUMN TWO IS NOT THE OWNER.
	Bedroom #4: Office				
	Laundry:	$\overline{\checkmark}$			
Ceiling	•				
Semini	General Type & Condition:	$\overline{\square}$			Drywall, General condition appears serviceable.
	Kitchen Interior:	<u> </u>			, , ,
	Master Bath:	\square			
	Hall Bath:	<u>v</u>			
		<u>v</u>			
	Entry / Foyer / Hall:	Ľ	Ц	ш	

Report: 901 orleans dr, ruston 01-14-2020 Address: 901 Orleans Dr

Page 33

		OK	MM	RR	
	Living Room:	<u> </u>			
	Dining Room:				
	Master Bedroom:	$\overline{\mathbf{A}}$			
	Bedroom #2:	\checkmark			
	Bedroom #3: Front				
	Bedroom #4: Office	$\overline{\checkmark}$			
	Laundry:	\checkmark			
Floors	::				
	General:	$\overline{\mathbf{A}}$			General condition of flooring throughout the home are in serviceable condition.
	Kitchen Interior:	$\overline{\checkmark}$			
	Master Bath:	$\overline{\checkmark}$			
	Hall Bath:	\checkmark			
	Entry / Foyer / Hall:	\checkmark			
	Living Room:	$\overline{\checkmark}$			
	Dining Room:	$\overline{\checkmark}$			
	Master Bedroom:	$\overline{\checkmark}$			
	Bedroom #2:	$\overline{\mathbf{V}}$			
	Bedroom #3: Front	$\overline{\mathbf{Q}}$			
	Bedroom #4: Office	$\overline{\mathbf{Q}}$			
	Laundry:	$\overline{\checkmark}$			
Closet	ts:				
	General:	$\overline{\checkmark}$			General condition appears serviceable.
	Entry / Foyer / Hall:	\checkmark			
	Master Bedroom:	$\overline{\checkmark}$			
	Bedroom #2:	\checkmark			
	Bedroom #3: Front	$\overline{\checkmark}$			
	Bedroom #4: Office				
Smoke	e / Fire Detector:	_	_	_	
	General:				Noted, but not tested.

Report: 901 orleans dr, ruston 01-14-2020 Address: 901 Orleans Dr

Page 34

LAUNDRY AREA

Laundry appliances are not tested or moved during the inspection and the condition of any walls or flooring hidden by them cannot be judged. Drain lines and water supply valves serving washing machines are not operated. Water supply valves may be subject to leaking if turned. See Plumbing and Electrical pages for more details about those types of system components.

Laundry:

Location: Service area main floor.

OK MM RR

Fuel System: \square \square Gas service pipe is provided.



Dryer Vent:
□ □ A dryer vent is provided,

GARAGE - CARPORT

Determining the heat resistance rating of firewalls is beyond the scope of this inspection. Flammable materials should not be stored within closed garage areas. Garage door openings are not standard, so you may wish to measure the opening.

to ensure that there is sufficient clearan garages, particularly with slabs on-grad	ice to accommodate your vehicles. It is not uncommon for moisture to penetrate de construction, and this may be apparent in the form of efflorescence or salou may want to have any living space above the garage evaluated further by a cally vulnerable.
Type:	Attached, Two car.
	Attached, 1 Wo car.

		100	State of the last	THE PERSON NAMED IN	
Roof:		OK	N 4N 4	DD	
(Condition:	OK □	MM		Same as house, See house roof report.
Ceiling					
(Condition:				Wood.
Garage	Door:				
	Material - Condition:	\checkmark			Metal with windows.
			$\overline{\checkmark}$		Deterioration noted at base of door trim.
	Door Operator			No.	Automatic door an argue (a) a constituted. Automatic reverse facture is
I	Door Operator:	Ø			Automatic door opener(s)- operational, Automatic reverse feature is operational.
Garage	Walls:				
	Type & Condition:	\checkmark			Wood, General condition appears serviceable.
Floor:	Condition:	V			Typical cracks noted.
Floor:	Type & Condition:				Wood, General condition appears serviceable.

Report: 901 orleans dr, ruston 01-14-2020 **Address:** 901 Orleans Dr Page 36

SPRINKLER SYSTEM

It is not within the scope of this report to determine the degree of salinity or volume of any well water. Inquire with the sellers of the property or check with the local agricultural extension service for these tests. We suggest you have the sellers instruct you as to the operation of this system. Ongoing maintenance of damaged or clogged sprinkler heads is necessary with most sprinkler systems.

OK	MM	RR	
			Not part of this inspection.

OUTBUILDING

Structure & Foundation

OK MM RR \Box \Box Not part of this inspection.

