,

RE: 462 Hogan Rd Ruston, la



Dear :Twin Creeks Realty

At your request, a visual inspection of the above referenced property was conducted on November 7, 2019. An earnest effort was made on your behalf to discover all visible defects, however, in the event of an oversight, maximum liability must be limited to the fee paid. The following is an opinion report, reflecting the visual conditions of the property at the time of the inspection only. Hidden or concealed defects cannot be included in this report. No warranty is either expressed or implied. This report is not an insurance policy, nor a warranty service.

SUMMARY OF AREAS REQUIRING FURTHER EVALUATION

IMPORTANT: The Summary is not the entire report. The complete report may include additional information of concern to the client. It is recommended that the client read the complete report. The entire Inspection Report, including the Standards of Practice, limitations and scope of Inspection, and Pre-Inspection Agreement must be carefully read to fully assess the findings of the inspection. This list is not intended to determine which items may need to be addressed per the contractual requirements of the sale of the property. Any areas of uncertainty regarding the contract should be clarified by consulting an attorney or real estate agent.

It is strongly recommended that you have appropriate licensed contractors evaluate each concern further and the entire system for additional concerns that may be outside our area of expertise or the scope of our inspection BEFORE the close of escrow. Please call our office for any clarifications or further questions.

Here is a list of concerns that need further evaluation or repair by appropriately Licensed Contractors.

EXTERIOR

Exterior Walls:

Materials & Condition:

Cracks in vinyl siding noted in some areas.

Exterior Doors:
Rear Entry Door: Store Room
Metal, Deterioration at base of frame.

ELECTRICAL SYSTEM

Attic Wiring:

Open junction boxes are noted.

HEATING - AIR CONDITIONING

Heating Equipment:

General Operation & Cabinet:

Unit disassembled at time of inspection, not tested.

Air Conditioning:

System Condition:

Interior Unit disassembled at time of inspection. Not tested.

KITCHEN - APPLIANCES

Kitchen Interior:

Refrigerator:

Refrigerator is plugged into a GFCI protected outlet.

INTERIOR ROOMS

Closets:

General:

General condition appears serviceable. Globs are recommended on light fixtures in closets.

Other minor items are also noted in the entire inspection report and should receive eventual attention, but do not affect the habitability of the house and the majority are the result of normal wear and tear.

Thank you for selecting our firm to do your pre-purchase home inspection. If you have any questions regarding the inspection report or the home, please feel free to call us.

Sincerely,

Robert Smith LHI#10796 InspectionSmith